

SCAG POWER EQUIPMENT

SERVICE INFORMATION SHEET 46

Ogura Clutch Maintenance

As you are aware, the Ogura electric PTO clutch is working extremely well. However, we have had several Ogura clutches returned to the Scag Warranty Department as failed units when all that was required was an airgap adjustment.

If the airgap is out of adjustment, the clutch may fail to engage or slip during cutting. In a case where the clutch has been slipping, the airgap should be adjusted and the clutch should be reburnished. Airgap settings should be checked every 500 hours or annually, whichever comes first. This adjustment should be performed more often in heavier use situations.

Reference the Servicing Scag from A to Z Video Series, Fundamentals Section for detailed information regarding the proper maintenance and testing of the electric PTO clutch.